

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2025

Submitted Date:

06/09/2025

Document Number:

707801638

FIELD INSPECTION FORM

Loc ID 322404	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 19 Number of Comments 6 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 10770 Name of Operator: VISION ENERGY LLC Address: P O BOX 370 City: IGNACIO State: CO Zip: 81137				
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE				

Contact Information:			
Contact Name	Phone	Email	Comment
, Vision		mollieo@maralexinc.com	All inspections
, Vision		mrinc20@maralexinc.com	
, Vision		pbechtolt@maralexinc.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210419	WELL	TA	11/01/2020	GW	045-06175	BALDY CREEK UNIT 1-17	TA

General Comment:

[CECMC Inspection Report Summary](#)
 On Tuesday 6/3/2025, I, Inspector Scott Ramsey, conducted a follow up inspection/audit at Vision Baldy Creek 1-17, at Location # 322404 in Garfield county Colorado.
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
 While there, I observed well shut it. Last MIT was preformed 7/14/2023. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

C/A's from previous inspection document # 708904948 have not been addressed therefore all C/A's remain the same.
 During this inspection the following compliance issues were observed:

1. Signs/Marker - Tank label on production tank contains inaccurate info/does not comply with CECMC rules with a CA date of 12/02/2024.
2. Housekeeping - Open ended piping/available for entry by wildlife/wildlife hazard with a CA date of 11/09/2024
3. Equipment - Meter calibration info not conspicuously posted with a CA date of 12/02/2024
4. Equipment - Open ended load line with a CA date of 11/09/2024
5. Tanks & Berms - Secondary containment is insufficient/does not comply with CECMC secondary containment rules with a CA date of 11/22/2024
6. Location is over grown with vegetation.
Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank label on production tank contains inaccurate info/does not comply with CECMC rules		
Corrective Action:	Comply with CECMC tank labeling rules	Date:	12/02/2024
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input type="text" value="970-563-0082"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>
Good Housekeeping:			
Type	OTHER		
Comment:	Open ended piping/available for entry by wildlife/wildlife hazard		
Corrective Action:	Comply with CECMC wildlife rules	Date:	11/09/2024
Type	WEEDS		
Comment:	Weeds encroaching on equipment in multiple areas		
Corrective Action:	Remove weeds	Date:	07/06/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Horizontal Heated Separator	#		corrective date
Comment:	<input type="text"/>		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible		

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter calibration info not conspicuously posted		
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.	Date:	12/02/2024
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open load lines		
Corrective Action:	All load lines will be capped or plugged	Date:	11/09/2024
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment is insufficient/does not comply with CECMC secondary containment rules. Additionally secondary containment is overrun with vegetation & compromised.			
Corrective Action:	Comply with CECMC secondary containment rules			Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210419 Type: WELL API Number: 045-06175 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: [Shut In](#)
[Last produced September 2009](#)
[Last MIT 06/13/2023 - document # 403444969](#)

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Light compaction in some areas
Compaction						Small amount of light compaction
Gravel						Sparse to none in areas
Culverts						
		Ditches				
		Culverts				
		Gravel				Sparse to none in areas
Ditches						
Other						Cut slope showing signs of lack of stabilization

Comment: [Cut slope showing some signs of lack of stabilization](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801643	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7087959