

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2025

Submitted Date:

06/03/2025

Document Number:

699700474

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**  
 ECMC Operator Number: 10844  
 Name of Operator: QB ENERGY OPERATING LLC  
 Address: 1001 17TH STREET SUITE 1600  
 City: DENVER State: CO Zip: 80202

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 2 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Cholas, Nick		nick.cholas@state.co.us	
,		ecmc.inspections@qb-energy.com	
Longworth, Mike		mike.longworth@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**General Comment:**  
 ECMC Environmental Inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: See Initial Form 19 Doc #404205884 and Supplemental Form 19 Doc #404214966 for more information. ECMC staff John Heil and Nick Cholas conducted an Environmental Inspection of the point of release as well as the irrigation ditch and Middle Mamm Creek. An excavation containing the produced water flowline (P11SW Injection Waterline) was observed around the point of release which was approximately five (5) feet deep. ECMC staff did not observe any visible impacts on the irrigation ditch or Middle Mamm Creek. Potentially impacted material was removed adjacent to the irrigation ditch, access road and Middle Mamm Creek. See attached Photo Log for details.

Corrective Action: Comply with COAs on Form 19 Initial and Supplemental.

Date: \_\_\_\_\_

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404227137	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7079353">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7079353</a>
699700475	20250519 Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7079352">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7079352</a>