

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2025

Submitted Date:

06/03/2025

Document Number:

719500024

FIELD INSPECTION FORMLoc ID 335459 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Popejoy, Dusty		dusty.popejoy@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262832	WELL	PR	10/06/2003	GW	045-08058	GM 332-27	PR
262833	WELL	PR	07/01/2011	CBM	045-08059	GM 32-27	PR
301667	WELL	PR	05/01/2012	GW	045-18211	GM 22-27	PR
301668	WELL	PR	04/16/2011	GW	045-18212	GM 522-27	PR
301670	WELL	PR	04/16/2011	GW	045-18214	GM 432-27	PR
301671	WELL	PR	04/16/2011	GW	045-18215	GM 421-27	PR
301672	WELL	PR	04/16/2011	GW	045-18216	GM 321-27	PR
301673	WELL	PR	10/01/2024	GW	045-18217	GM 31-27	PR
301674	WELL	PR	04/16/2011	GW	045-18218	GM 521-27	PR
301675	WELL	PR	04/16/2011	GW	045-18219	GM 541-27	PR
301676	WELL	PR	04/16/2011	GW	045-18220	GM 21-27	PR
301677	WELL	PR	04/16/2011	GW	045-18221	GM 322-27	PR
301678	WELL	PR	03/11/2011	GW	045-18213	GM 431-27	PR
301679	WELL	PR	04/16/2011	GW	045-18222	GM 331-27	PR
301680	WELL	PR	04/16/2011	GW	045-18223	GM 531-27	PR
301681	WELL	PR	04/16/2011	GW	045-18224	GM 532-27	PR
301682	WELL	PR	04/16/2011	GW	045-18225	GM 34-22	PR

General Comment:

CECMC Audit Report Summary

On 5/22/2025 at approximately 11:55, Compliance Inspector Matthew Morris conducted a follow-up audit at TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE at Location ID #335459 in Garfield County, Colorado.

During the audit, the following compliance issues were observed:

1) Illegible wellhead signs

A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

LocationOverall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Illegible wellhead signs.		
Corrective Action:	Install signs to comply with Rule 605.d.	Date:	07/04/2025
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970)285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 17		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 19		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Line heater		
Corrective Action:		Date:	
Type: Bradenhead	# 17		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Plunger Lift	# 17		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal					
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)	80 bbls				
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities				
Facility ID:	262832	Type:	WELL	API Number: 045-08058 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	262833	Type:	WELL	API Number: 045-08059 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301667	Type:	WELL	API Number: 045-18211 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301668	Type:	WELL	API Number: 045-18212 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301670	Type:	WELL	API Number: 045-18214 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301671	Type:	WELL	API Number: 045-18215 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301672	Type:	WELL	API Number: 045-18216 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	301673	Type:	WELL	API Number: 045-18217 Status: PR Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>			
Comment:			
Corrective Action:			Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	301674	Type: WELL	API Number: 045-18218 Status: PR Insp. Status: PR
<u>Producing Well</u>			
Comment:			
Corrective Action:			Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	301675	Type: WELL	API Number: 045-18219 Status: PR Insp. Status: PR
<u>Producing Well</u>			
Comment:			
Corrective Action:			Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	301676	Type: WELL	API Number: 045-18220 Status: PR Insp. Status: PR
<u>Producing Well</u>			
Comment:			
Corrective Action:			Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	301677	Type: WELL	API Number: 045-18221 Status: PR Insp. Status: PR
<u>Producing Well</u>			
Comment:			
Corrective Action:			Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	301678	Type: WELL	API Number: 045-18213 Status: PR Insp. Status: PR
<u>Producing Well</u>			
Comment:			
Corrective Action:			Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	301679	Type: WELL	API Number: 045-18222 Status: PR Insp. Status: PR
<u>Producing Well</u>			
Comment:			
Corrective Action:			Date: <input type="text"/>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	301680	Type: WELL	API Number: 045-18223 Status: PR Insp. Status: PR
<u>Producing Well</u>			
Comment:			

Corrective Action:		Date:							
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	301681	Type:	WELL	API Number:	045-18224	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	301682	Type:	WELL	API Number:	045-18225	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Rip Rap				
				Material Handling And Spill Prevention		
		Culverts				
		Check Dams				
Compaction						
Gravel						
		Compaction				
		Gravel				
Berms						
		Sediment Traps				
		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404228109	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7080648
719500025	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7080646