

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 06/4/2025



Photo # 7707 Entrance to location

Photo # 7730 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 06/4/2025



Photo # 7709 Location



Photo # 7718 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 06/4/2025



Photo # 7729 Location



Photo # 7743 SW corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 06/4/2025



Photo # 7744 SE corner of location



Photo # 7745 NE corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 06/4/2025



Jun 4, 2025 at 2:16:24 PM
+39.226463,-108.209301 ±2.40m
De Beque



Jun 4, 2025 at 1:53:46 PM
+39.226013,-108.209066 ±3.75m
De Beque

Photo # 7746 NW corner of location

Photo # 7715 Intermediate Casing valve is buried/not in compliance with CECMC rules

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 06/4/2025



Photo # 7716 Intermediate Casing valve is buried/not in compliance with CECMC rules

Photo # 7717 Small amount of weeds around wellhead

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Horseshoe Canyon/1-34 Pad

Location ID: 312481

Date: 06/4/2025



Photo # 7733 Tank is dented, also rusted in most areas



Photo # 7739 Tank is dented, also rusted in most areas