



An excavation remains open at the spill location (former wellhead). Groundwater is visible at the base of the excavation. Gray staining is visible on portions of the excavation sidewalls.

WGS84 $\pm 15\text{ft}$ 40.11525, -104.99686 $\Delta^m_{\pm 3\text{m}}$ 1513 $\triangle^{\circ, T}_{\pm 11}$ NW332



ECMC
Environmental
Field Inspection



Jillson 5
© 22-May-25 08:59:05 AM
ECMC Environmental Inspection

Trenches were observed along the flowline path. A flowline was observed adjacent to the southeastern trench.



WGS84 40.11528, -104.99689 m 1513 °T NW317
±14ft ±3m ±11

ECMC
Environmental
Field Inspection



Jillson 5
© 22-May-25 08:59:18 AM
ECMC Environmental Inspection

Salt crusting was visible within the southeastern trench. Orange construction fencing and plastic tape partially surrounds the trench but does not fully encompass the perimeter.

WGS84 40.11551, -104.99709 Δ $\pm 3m$ 1512 \angle ± 11 SE150



ECMC
Environmental
Field Inspection



Jillson 5
© 22-May-25 09:01:34 AM
ECMC Environmental Inspection

Debris was visible within the northwest trench, partially obscuring visibility. Orange construction fencing and plastic tape partially surrounds the trench but does not fully encompass the perimeter.