



Form Resolution To Document Number: 696307330 & 696307553

Horsetail 33M Photo Documentation

Submit FIRR for Doc#: 696307330 & 696307553

Drafted By:



Melissa Parrish

Cell: (720)795-3257

Email: Mparrish@fundareresources.com

Production/ Compliance/ Regulatory/ Health & Safety




Horsetail 33M –

Unmarked Risers at Tanks & Flare Site –

All Unmarked Risers Have Been Properly Labeled

–

Please See Above Photo



Horsetail 33M –

Unmarked Risers at Tanks & Flare Site –

All Unmarked Risers Have Been Properly Labeled

–

Please See Above Photo



Horsetail 33M –

Repair or Install Berms or Other Secondary Containment Devices per Rule
603.o. –

All Damaged Tank Berms Have Been Properly Replaced In Compliance With
Rule 603.o.

–

Please See Above Photo



Horsetail 33M –

Repair or Install Berms or Other Secondary Containment Devices per Rule
603.o. –

All Damaged Tank Berms Have Been Properly Replaced In Compliance With
Rule 603.o.

–

Please See Above Photo