

# Final Reclamation and Stormwater Inspection

June 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327396

Well Name: GLENS GAS UNIT #12-6

Inspection Document #: 718600656

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GLENS GAS UNIT #12-6  
Location ID: 327396



**Photo 1.** Looking east across the wellbore. The well location is adjacent to fallow cropland. Undesirable weed Kochia is present throughout the location. A monitoring well/pvc pipe is present near the wellbore (red circle).



**Photo 2.** Looking north across the well location down the former access road. See photo 1 comments.



Inspection Photos  
Location Name: GLENS GAS UNIT #12-6  
Location ID: 327396



**Photo 3.** PVC pipe near the wellbore.



**Photo 4.** Looking south across the tank battery location. The tank battery is located 1500 ft to the southeast. The tank battery is located in an active crop field.



Inspection Photos  
Location Name: GLENS GAS UNIT #12-6  
Location ID: 327396



**Photo 5.** Picture taken on the east side of location. T posts and net are present around a box set in ground.



**Photo 6.** Looking south across the tank battery. Bare soil is present approximately where the PWV and tanks were located.



Inspection Photos  
Location Name: GLENS GAS UNIT #12-6  
Location ID: 327396



**Photo 7.** Looking south across the southern portion of the tank battery. A bare soil is present.



**Photo 8.** The bare patches appear to have been seeded/cultivated.