

Final Reclamation and Stormwater Inspection

June 6, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 329859

Well Name: GLENS VV #6-14

Inspection Document #: 718600660

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GLENS VV #6-14
Location ID: 329859



Photo 1. Looking south down the former access road from the well location. Portions of the road remain as ditch access or converted to paved walking path.



Photo 2. Looking south from wellbore. No oil and gas equipment remains on location. A large mound of soil is noticeable in this open space around the wellbore area. A large amount of Kochia is present on the mound of soil.

Inspection Photos
Location Name: GLENS VV #6-14
Location ID: 329859



Photo 3. Looking east from the well location. See photo 2 comments.



Photo 4. Looking north from the well location. The mound is visible in this picture.

Inspection Photos
Location Name: GLENS VV #6-14
Location ID: 329859



Photo 5. Looking east from the well location. See photo 2 comments.

Inspection Photos
Location Name: GLENS VV #6-14
Location ID: 329859



Photo 6. Google earth aerial imagery taken 09/2019. It appears that during the construction of residential housing the well location/ open space was used as a soil stockpile location. The soil pile appears to have been spread over the open space resulting in significant non-oil and gas earthworks.

