

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2025

Submitted Date:

06/05/2025

Document Number:

713302108**FIELD INSPECTION FORM**Loc ID 317874 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**19 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Revas, Robbie		robbie.revas@state.co.us	
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240105	WELL	PR	03/01/2025	GW	123-07893	HAUDRICH 1	PR

**General Comment:**[well site and facility inspection](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	good		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:	post and wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric disconnect, metal panels		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	post and wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	post and wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	post and wire		

Corrective Action:		Date:	
<b>Equipment:</b>		corrective date	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: automation/electric panels			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment: Unmarked dead men			
Corrective Action: Comply with Rule 1003e		Date: 06/02/2024	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: electric			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: piped to surface			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	50 Bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: berm washed out				

Corrective Action: <b>Comply with Rule 1002</b>					Date: <u>06/02/2024</u>	
Contents		#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL		2	300 BBLS	STEEL AST		,
Comment:						
Corrective Action:					Date:	
<b><u>Paint</u></b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b><u>Berms</u></b>						
Type	Capacity		Permeability (Wall)		Permeability (Base)	
Earth	Inadequate		Walls Insufficient		Base Insufficient	
Comment: <b>berm washed out</b>						
Corrective Action: <b>Comply with Rule 1002</b>					Date: <u>06/02/2024</u>	
<b><u>Venting:</u></b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b><u>Flaring:</u></b>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 240105

Type: WELL

API Number: 123-07893

Status: PR

Insp. Status: PR

Idle Well

Purpose: ☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment: Valves appeared to be closed at time of inspection

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/03/2025

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<div>Audit of scout card and related documents</div> <div>Follow up inspection as per Doc # 702403395, corrective actions appeared to have NOT been addressed</div> <div>Unmarked dead men, comply with Rule 1003e, corrective action date 6-2-2024</div> <div>2 Tank berms washed out, comply with Rule 1002 corrective action date 6-2-2024</div> <div>This inspection does not nullify any orders or NOAV from the ECMC</div>	kesterm	06/05/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404231603	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084583">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084583</a>
713302109	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084580">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084580</a>