

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2025

Submitted Date:

06/05/2025

Document Number:

710500539

**FIELD INSPECTION FORM**Loc ID 476172 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 96730

Name of Operator: WILLIFORD ENERGY COMPANY

Address: 6060 AMERICAN PLAZA SUITE 760

City: TULSA State: OK Zip: 74135

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Growns, Larry		lgrowns@willifordenergy.com	
Pamela Richards		prichards@willifordenergy.com	All Inspections
Longworth, Mike		mike.longworth@state.co.us	
Storts, Doug	(918) 495-2710	pds@willifordenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476172	LOCATION	AC			-	Rhoades Unit Gas Injection Flowline 3213S48W	EI
489565	SPILL OR RELEASE	AC	03/18/2025		-	Rhoades Unit Gas Injection Flowline	EI

**General Comment:**

This is an Environmental Inspection for the Rhodes Unit Gas Injection Flowline located in Cheyenne County, Colorado, Spill ID 489565.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Placard at entrance to location		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Other				
Comment:	At the time of inspection, impacted soils were observed at Latitude 38.87975; Longitude -102.813523 and Latitude 38.879750; Longitude -102.813523 Photo # 6			
Corrective Action:	Operator shall cleanup stained soils and securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			Date: <u>06/19/2025</u>

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	476172	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	489565	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: This is an Environmental Inspection for Spill ID 489565. Spill ID 489565 is beyond the 90-day closure window. Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure. The Form 19 Supplemental Report for closure was due by April 27, 2025. Remediation Project # 40325 is active. Operator shall submit a Form 19-s requesting closure for Spill ID 489565

Corrective Action: **Operator shall submit delinquent form(s) for this project. Comply with Rule 912.b.(6)**

Date: 06/19/2025

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

Lat \_\_\_\_\_

Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Waste Management:**

Type Management Condition GPS (Lat) (Long)

Oily Soil

Piles

Inadequate

Comment: Impacted soils stored on location, Per COA in Form 19-s Document # 403977643 for Spill ID 486489:

Operator states under Corrective Actions: The impacted soil has been excavated and hauled to the bio-remediation at Williford's gas plant yard where it was placed in lined containment. The contaminated soil was fertilized and stirred until it was clean. Operator shall provide a waste manifest in accordance with Rule 905. b. for the transport of materials.

In addition, the Operator shall provide evidence a Reuse and Recycling plan was approved for the treatment of E&P Waste at an off location Facility or provide a Facility Location ID for an approved E&P Waste Management Facility Per Rule 905.a.(3).

Corrective Action: **Supply requested data per Rule 206.**

Date: 07/03/2025

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404231412	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084374">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084374</a>
710500540	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084371">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7084371</a>