

# Inspection Photos

API: 073-06665

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 6/10/2025

County: LINCOLN



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south along the access road. Gravel along the road will need to be removed and the road will need to be reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:073-06665 | Date: 6/10/2025

## Inspection Photos



**Photo 2.** Facing south further down the road. There is erosion at this area of the road. The cattleguard will need to be removed.



## Inspection Photos



**Photo 3.** Facing southeast at the location. The location has not been recontoured and reclaimed.



## Inspection Photos



**Photo 4.** Facing orthwest at the location. Gravel has not been removed and soils are not decompacted and regraded.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:073-06665 | Date: 6/10/2025

## Inspection Photos



**Photo 5.** Drone aerial photo facing southeast at the location



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:073-06665 | Date: 6/10/2025

## Inspection Photos



**Photo 6.** Drone aerial photo facing northwest at the location.

