

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2025

Submitted Date:

06/06/2025

Document Number:

713400832

FIELD INSPECTION FORM

Loc ID 312496 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 18 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, LARAMIE		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Koch, Benjamin		bzkoch@blm.gov	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221780	WELL	PR	03/01/2018	GW	077-08382	HORSESHOE CANYON 2-34	PR

General Comment:

[CECMC Inspection/Audit Report Summary](#)

On 06/4/2025 at approximately 13:06 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at LARAMIE ENERGY LLC Horseshoe Canyon/2-34 Pad at Location ID #312496 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Equipment - Dehydrator housing is damaged and available for entry by wildlife with a CA date of 06/13/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign on meter house		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign is becoming illegible, refer to photos		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	1-800-891-6191/911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Small amount of staining in meter house, refer to photos		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Debris north of wellhead, refer to photos		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Pipe rail		
Corrective Action:		Date:	

Equipment:

Type	#	Comment	Corrective Action	Date
Bird Protectors	# 1			
Horizontal Heated Separator	# 1			
Gas Meter Run	# 1			
Deadman # & Marked	# 2			
Dehydrator	# 1	Dehydrator housing is damaged and available for entry by wildlife	Comply with CECMC wildlife rules	06/13/2025
Plunger Lift	# 1	Well on plunger lift		
Bradenhead	# 1	No form of pressure monitoring equipment. Bradenhead valve is accessible		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment:	Staining on side of tank, refer to photos Tank not equipped with telemetry				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	60 bbls
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 221780 Type: WELL API Number: 077-08382 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Light compaction
		Ditches				
Compaction						Light compaction
Berms						
Ditches						
		Berms				
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment for corrective action also Housekeeping, Tanks and Berms & Signs/Marker for comments.	popejoyd	06/06/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404232363	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7085384
713400833	Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7085383