

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/12/2025

Submitted Date:

06/13/2025

Document Number:

707603974

FIELD INSPECTION FORM

Loc ID 302543 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_ecmc_engineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299261	WELL	TA	05/26/2020	OW	123-29305	WELLS RANCH USX AA 13-16	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations: Mechanical set; Initial plug.
Battery: Abandoned.
Abandoned Battery SE corner GPS coordinates: 40.482870 / -104.380730
Well GPS coordinates: 40.481277 / -104.377906

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 299261 Type: WELL API Number: 123-29305 Status: TA Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____ Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 6468' Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: 2025/06/12:
 Plugging Operations: Mechanical set; Initial plug. No cement.
 2025/06/12: JSA attached as photo to this report.

IWP –
 SFC – 0 PSI CSG –650 PSI TBG – 650 PSI
 CREW TRAVEL HSM., REVIEW SIF HAZARDS. PERFORM SWC'S & INSPECTIONS (WSEA 2-A/XIJG). CHECK PRESSURES. RU HARDLINES AND GROUNDING. SETUP REDZONES/EXCLUSION ZONE CONTROL SYSTEM. COMPLETE FORM17. ACCUM
 DRAWDOWN TEST. PT HARDLINE, 2.375" PIPE & BLIND RAMS (WSEA 9-A/XIJG). KILL WELL W/ 143 BBLs OF FW, NO HYDROCARBONS IN RETURNS. WELLSI. RU SERVICE UNIT. OPENED WELL AND VERIFIED WELL WAS STATIC FOR 15 MIN (WSEA 10-A/XIJG). ND WELLHEAD. NU 7-1/16" BOPE & 7-1/16" 5K X 5K PORTED SPOOL (WSEA 8-A/XIJG). R/U FLOOR. TEST BOP CONNECTION TO 250-300PSI LOW/2000PSI FOR HIGH FOR 5MIN EACH (WSEA 9-A/XIJG). OPS SUSPEND FOR V&V. UNLAND TBG HANGER, 29K. PULL HANGER. TOO. SB 80 JTS L/D 138 JTS OF 2.375" 4.7# J55 TBG, TRICKLED 33 BBLs TO MAINTAIN HYDROSTATIC. HSM W/ AXIS WL (WSEA 2-B/XIJG). RUWL. 1 ST RIH & SET 4.50" CIBP@6468'MD. POOH. 2 ND RIH, DB2SK (TOC@6442'MD) POOH. LOAD (27 BBLs) & PRESSURE TEST PLUG TO 1500PSI FOR 15MIN. GOOD TEST NO PRESSURE LOSS WITNESSED, DOCUMENTED IN WV (WSEA 10-A/XIJG). OPS SUSPENDED DUE TO WEATHER. RDWL. WELLSI. DRAIN EQUIPMENT. DEBRIEF/SDFN

Corrective Action: _____ Date: _____

Workover

Comment:

2025/06/12:
Plugging Operations: Mechanical set; Initial plug. No cement.
2025/06/12: JSA attached as photo to this report.

Workover Contractor: Axis Energy Services, Rig #716.
Cement Contractor: Axis Energy Services.

Reference:
Form 6N on file. Notice of Intent to Abandon date: 04/29/2025. Approved.
Form 42 on file. Notice of MIRU. Start Date: 06/06/2025. Approved.
Form 42 on file. Notice of Plugging Operations. Start Date: 06/06/2025. Approved.
Email on file. Notice of Plugging Operations. Start Date: 06/12/2025. Approved.
Form 27 on file. Remediation Workplan. Date: 05/21/2025. Approved.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On THU 06/12/2025 at approximately 14:00 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH USX AA-66N63W/13SESE Location ID: 302543 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Mechanical set; Initial plug. Battery: Abandoned. Abandoned Battery SE corner GPS coordinates: 40.482870 / -104.380730 Well GPS coordinates: 40.481277 / -104.377906</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	06/13/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603977	Inspection photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7095575