

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/13/2025

Submitted Date:

06/13/2025

Document Number:

707603978

FIELD INSPECTION FORM

Loc ID: 302543 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_ecmc_engineering@state.co.us	
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299261	WELL	TA	05/26/2020	OW	123-29305	WELLS RANCH USX AA 13-16	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER / CEMENTING** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Plugging Operations: Cementing; Cement-surface.
Battery: Abandoned.
Abandoned Battery SE corner GPS coordinates: 40.482870 / -104.380730
Well GPS coordinates: 40.481277 / -104.377906

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:		Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 299261 Type: WELL API Number: 123-29305 Status: TA Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Axis Energy Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 4075'-2491' Cement Volume (sx): 192 sxs

Good Return During Job: _____ Cement Type: Class "G" Neat 15.8#

Comment: 2025/06/13:
 Plugging Operations: Cementing; Cement-surface.
 2025/06/13: JSA attached as photo to this report.

Workover Contractor: Axis Energy Services, Rig #716.
 Cement Contractor: Axis Energy Services.

IWP –
 SURFACE – 0 PSI CASING –0 PSI
 CREW TRAVEL. HSM., REVIEW SIF HAZARDS. PERFORM SWC'S &
 INSPECTIONS (WSEA 2-A/XIJG). CHECK PRESSURES
 AND VERIFY GROUNDING. HSM W/AXIS WL (WSEA 2-B/XIJG). RUWL. 1 st RIH
 & LOG 850'MD-SFC. 2 ND RIH & SET 4.500"
 CIBP@4075'MD. POOH. 3 RD RIH, DB2 SK(TOC@4049'MD) POOH. 4 TH RIH &
 SET 4.500" CIBP@2491'MD. POOH. INFLOW
 TEST FOR 30 MINS TO VERIFY NO PRESSURE. RECEIVED STATE APPROVAL TO
 MOVE PERFS UP. 6 TH RIH, CSG PUNCH 1-
 6SPF@590'MD W/ 500PSI ON CSG. PRESSURE BLED OFF. POOH. RDWL.
 ESTABLISH FWD CIRC. DOWN PCSG OUT
 PERFS@590'MD & UP SCSCG. CIRCULATE 2X ANN VOL. OF 56 BBLS (2 BPM @
 275PSI). PERFORM 5 MIN. FLOW CHECK.
 TIH W/81 JTS OF 2.375" 4.7# J55 TBG & TAG CIBP @ 2491'MD. LD 1 JT PU (2)
 2.375" X 10' TBG SUB. HSM W/AXIS CMT
 (WSEA 2-C/XIJG). RUCMTUNIT. PT. BREAK CIRC. PUMP 10 SK G NEAT (2 BBLS,
 1.15Y., 15.8#). DISPLACE W/9.0 BBLS FW.
 BPLUG 2491'-2391'MD. TOO. LD (2) SUBS & 16 JTS TO 1998'MD REVERSE 15
 BBLS. LD 43 JTS OF 2.375" 4.7# J55 TBG.
 21 JTS REMAINING EOT@650MD. HSM W/ AXIS CMT (WSEA 2-D/XIJG).
 RUCMTUNIT. PT. BREAK CIRC. PUMP 10BBLS
 CHEM WASH, 5 BBLS FW SPACER, FOLLOWED BY 180 SK G NEAT CMT TO SFC
 (37 BBLS, 1.15Y., 15.8#). TOO. LD 21 OF
 2.375" 4.7# J55 TBG. RD FLOOR. ND 7-1/16" 5K BOPS, 7-1/16" 5K X5K PORTED
 SPOOL. TOPOFF, RDCMTUNIT. NU
 WELLHEAD. WELLSI. RD SERVICE UNIT. BOTTOM OUT TANKS. RD HARDLINE,
 REDZONE SYSTEMS; CLEAN LOCATION.

Corrective Action: _____ Date: _____

Workover

Comment:

Corrective Action:	<p>2025/06/13: Plugging Operations: Cementing; Cement-surface. 2025/06/13: JSA attached as photo to this report.</p> <p>Workover Contractor: Axis Energy Services, Rig #716. Cement Contractor: Axis Energy Services.</p> <p>Reference: Form 6N on file. Notice of Intent to Abandon date: 04/29/2025. Approved. Form 42 on file. Notice of MIRU. Start Date: 06/06/2025. Approved. Form 42 on file. Notice of Plugging Operations. Start Date: 06/06/2025. Approved. Email on file. Notice of Plugging Operations. Start Date: 06/12/2025. Approved. Form 27 on file. Remediation Workplan. Date: 05/21/2025. Approved.</p>	Date:
--------------------	--	-------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 06/13/2025 at approximately 14:00 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WELLS RANCH USX AA-66N63W/13SESE Location ID: 302543 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations: Cementing; Cement-surface. Battery: Abandoned. Abandoned Battery SE corner GPS coordinates: 40.482870 / -104.380730 Well GPS coordinates: 40.481277 / -104.377906</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	06/13/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603979	Inspection photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7095576