

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2025

Submitted Date:

06/09/2025

Document Number:

713400844

**FIELD INSPECTION FORM**

Loc ID: 312633      Inspector Name: Popejoy, Dusty      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 13 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 10433  
 Name of Operator: LARAMIE ENERGY LLC  
 Address: 1700 LINCOLN ST STE 3950  
 City: DENVER      State: CO      Zip: 80203

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Toews, Wesley		wtoews@blm.gov	
, LARAMIE		cogccnotifications@laramie-energy.com	
Katz, Aaron		aaron.katz@state.co.us	
Koch, Benjamin		bzkoch@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222062	WELL	PR	04/01/2018	GW	077-08664	HORSESHOE CANYON 3-34	PR

**General Comment:**

[CECMC Inspection/Audit Report Summary](#)

On 06/5/2025 at approximately 11:18 hours, Compliance Inspector Dusty Popejoy conducted a follow up inspection/audit at LARAMIE ENERGY LLC Horseshoe Canyon/3-34 Pad at Location ID #312633 in Mesa County, Colorado.

Please refer to inspection/audit 713400539 conducted on 12/10/2024, previous corrective action has been completed.

During the inspection/audit, the following compliance issues were observed:

1. Inspected Facilities - Well lacks wellbore diagram/not in compliance with CECMC rules with a CA date of 07/9/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

<b>Lease Road:</b>			
	Type	Access	
	comment:	Access	
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type	OTHER	
	Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.	
Corrective Action:			Date:
	Type	TANK LABELS/PLACARDS	
	Comment:		
Corrective Action:			Date:
	Type	WELLHEAD	
	Comment:		
Corrective Action:			Date:
	Type	OTHER	
	Comment:	Sign at entrance to location is weathered & cracked but still legible	
Corrective Action:			Date:
	Type	BATTERY	
	Comment:		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
	Comment:	1-800-891-6191/911	
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No  
 Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type	TANK BATTERY	
	Comment:	Hog panels	
Corrective Action:			Date:
	Type	WELLHEAD	
	Comment:	Pipe rail fencing	
Corrective Action:			Date:

<b>Equipment:</b>		corrective date
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	62 bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 222062 Type: WELL API Number: 077-08664 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

[Well lacks wellbore diagram/not in compliance with CECMC rules](#)

Corrective Action: [Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17](#)

Date: 07/09/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Compaction				Light compaction
		Berms				
Compaction						Light compaction
Berms						
Ditches						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Inspected Facilities for corrective action.</a>	popejoyd	06/09/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404233161	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7087153">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7087153</a>
713400845	Inspection-Audit Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7087149">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7087149</a>