

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2025

Submitted Date:

06/09/2025

Document Number:

708700112

FIELD INSPECTION FORM

Loc ID 325310 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 31250
Name of Operator: FRITZ & DIGMAN INC
Address: PO BOX 70024
City: ALBUQUERQUE State: NM Zip: 87197-

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Arleen		arleen@walsheng.net	
, DNR		dnr_cogccengineering@state.co.us	
Digman, Rebecca	505-379-8689	rcdigman@yahoo.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214538	WELL	SI	06/01/2023	OW	067-06141	DAKOTA FEE 1	EI

General Comment:

[Wellhead is actively venting methane. See attached video.](#)
[See corrective action to submit Form 27 with results of gas sampling.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	YES		
Comment:	Wellhead area is actively venting methane (see attached video)		
Corrective Action:	Operator shall investigate source of methane leak and determine isotopic chemistry of methane. Report findings on a Form 27 for Remediation 38333	Date:	06/30/2025

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 214538 Type: WELL API Number: 067-06141 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404234313	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7088258
708700113	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7088256
708700114	Gas leak video	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7088257