

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2025

Submitted Date:

06/17/2025

Document Number:

713602287

FIELD INSPECTION FORM

Loc ID 321151 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10560
Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME
Address: PO BOX 2326
City: VICTORIA State: TX Zip: 77902

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
HAHN, MIKE		mhahn@xeogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206158	WELL	SI	01/01/2025	GW	009-06574	GODFREY 1-19	RI

General Comment:

This is a follow up location inspection at the GODFREY #1-19 wellsite.
See good housekeeping comment for required maintenance.
See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	BATTERY			
Comment:	Sign has been reinstalled.			
Corrective Action:			Date:	

Emergency Contact Number:

Comment:			Date:	
Corrective Action:			Date:	

Good Housekeeping:

Type	WEEDS			
Comment:	There are weeds around the tank and equipment that need to be removed and controlled.			
Corrective Action:			Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		Open Top		
Comment:	The netting at the open top tank has been repaired and maintained.				
Corrective Action:				Date:	

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:	The secondary containment has been rebuilt and maintained.			
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713602288	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7099088