

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2025

Submitted Date:

06/17/2025

Document Number:

719000241

FIELD INSPECTION FORM

Loc ID: 325235 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87401

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Fields, Vanessa		vfields@logosresourcesllc.com	SJB inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214370	WELL	TA	07/01/2020	GW	067-05781	ESPINOSA 1	TA

General Comment:

Inspection Report Summary
On 06/17/25 I Inspector Charles Garcia conducted an on-site inspection.
Location: ESPINOSA 1
Operator: LOGOS OPERATING LLC
API#: 067-05781
County: LaPlata
PLUGGING OPERATIONS FORM 6 SUBMITTED ON 3/12/25 DOCUMENT #404124214. BRHD TEST WAS PERFORMED ON 4/28/25. CBL WAS PERFORMED 6/16/25 AND HAS BEEN SUBMITTED. CASING TEST PERFORMED AND HEALD 560 PSI FOR 15 MIN. WORKER CREW IN HOLE TAGED FIRST PLUG AT 4978 FT.
WELL BORE IS FULL OF H2O CREW WILL UNLOAD WELL WITH AIR UNIT AND START DRILLING PLUG #5. ALL OPERATIONS GOING AS PLANED.

Location

Overall Good:

Emergency Contact Number:

Comment: 970-247-6916
911 emergency

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 214370 Type: WELL API Number: 067-05781 Status: TA Insp. Status: TA

BradenHead

Date of Last Brhd Test: 04/28/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000244	LOCATION PICS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7099665