

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/16/2025

Submitted Date:

06/17/2025

Document Number:

707603990

**FIELD INSPECTION FORM**

Loc ID 415625 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415625	LOCATION	AC			-	JASMINE AC 21-16	AO

**General Comment:**

This is a BATTERY inspection.  
Well(s): 1: Producing | PR.  
Battery: Active.

Centralized Battery serves 1 Location ID (415625).  
(Well(s): 1: Producing | PR).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):  
A.) Field Inspection Report doc. #707603988 and/or Location ID #415625 for PR, SI Well(s) info.  
B.) Field Inspection Report doc. #707603990 and/or Location ID #415625 for Battery / Facility, Equipment info.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Battery site: Nitrogen. Placards.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Posted.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Braided wire.		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Braided wire.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Braided wire. Surrounded by earth berms.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 3		
Comment:	Battery site: 1: Nitrogen tank(s) for instrument air. 2: ECD Scrubber(s).		
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:	1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. 1: Separator vapor line combustor(s). Controls Separator(s) vapors. Pilots: ON.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	1: Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration <= 1 year. Last calibration: 03/04/2025.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Location ID (415625). (Well(s): 1: Producing   PR). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	

Other (Capacity) 53 Bbls.	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.553072,-104.434259	
Comment:						
Corrective Action:				Date:		

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:				Date:	

**Wells Served By Facilities Above**

API Number
123-31186

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 415625 Type: LOCATION API Number: - Status: AC Insp. Status: AO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On MON 06/16/2025 at approximately 15:41 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: NOBLE ENERGY INC                      Facility Name: Pending                      Facility ID: Pending                      Location Name: JASMINE AC/21-16                      Location ID: 415625                      Well Name(s):                      See photo(s) #6 attached to this report.                      API:                      See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #6 attached to this report.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Producing   PR.                      Battery: Active.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	06/17/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603991	Inspection photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7099795">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7099795</a>