

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2025

Submitted Date:

06/11/2025

Document Number:

719000199**FIELD INSPECTION FORM**Loc ID 333346 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10755Name of Operator: MORNINGSTAR OPERATING LLCAddress: 400 W 7TH STCity: FORT WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kittinger, Eric		ekittinger@mspartners.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298809	WELL	PR	02/10/2010	GW	007-06268	DUNGAN 32-5 5-5	PR

General Comment:

Inspection Report Summary
 On 6/10/25 I Inspector Charles Garcia
 conducted an on-site inspection.
 Location: DUNGAN
 Operator: MORNINGSTAR OPERATING LLC
 API#: 007-06268
 County: ARCHULETA

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	505-325-6800 911 EMERGENCY	
Corrective Action:	CONTACT # ON LOCATION SIGN IS DISCONNECTED. UPDATE CONTACT # ON LOCATION SIGN.	Date: 06/18/2025

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	6FT CHAINLINK		
Corrective Action:		Date:	

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	ELECTRIC		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CALIBRATION RECORD WITHIN COMPLIANCE		
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	ELECTRIC PANEL CHEMICAL INJECTION CONTAINER WITH SPILL PREVENTION		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	298809	Type:	WELL	API Number:	007-06268	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	10/24/2024	Annual Brhd Completed?	Yes						
Last Brhd Test Results	Initial Surf Csg Pressure:	3	Fluid Type:	NONE					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404236522	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7090916
719000200	LOCATION PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7090910