

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2025

Submitted Date:

06/11/2025

Document Number:

708906716

FIELD INSPECTION FORM

Loc ID 334952	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 15 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 10844 Name of Operator: QB ENERGY OPERATING LLC Address: 1001 17TH STREET SUITE 1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268222	WELL	PR	11/29/2004	GW	045-09246	HMU 10-4D(F10)	PR
268224	WELL	PR	05/28/2004	GW	045-09247	HMU 10-3D (F10W)	PR
268225	WELL	SI	02/01/2025	GW	045-09248	HMU 10-6D (F10W)	SI
268226	WELL	PR	11/29/2004	GW	045-09249	HMU 10-5D (F10W)	PR

General Comment:**CECMC Inspection/Audit Report Summary**

On 06/11/2025 at approximately 15:35 hours, I, Compliance Specialist, Wayne Smelser
 Conducted a follow up inspection/audit at QB ENERGY OPERATING LLC HMU 10-4D (F10) Pad.
 Location # 334952 in Garfield County Colorado.

Please refer to inspection 707801510 conducted on 03/31/2025, previous corrective action has been completed.
 Location is within High Priority/Density/Black Bear Habitat areas.
 While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Inspected Facilities - Multiple wells lack wellbore diagrams/not in compliance with CECMC rules with a CA date of 07/11/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection/audit report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-2615		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 4		corrective date
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 268222 Type: WELL API Number: 045-09246 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger liftWell lacks wellbore diagram/not in compliance with CECMC Rule 420Additionally the HMU 10-3D (F10W), HMU 10-6D (F10W) & HMU 10-5D (F10W) wells also lack wellbore diagrams/not in compliance with CECMC Rule 420Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17Date: 07/11/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 268224 Type: WELL API Number: 045-09247 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger liftWell lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 268225 Type: WELL API Number: 045-09248 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Shut InLast produced January 2025Well lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 268226 Type: WELL API Number: 045-09249 Status: PR Insp. Status: PR**Producing Well**Comment: Producing, well on plunger liftWell lacks wellbore diagram/not in compliance with CECMC Rule 420

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				Light compaction in sections
		Culverts				
Gravel	Fail					Insufficient gravel
Berms						
Rip Rap						
Ditches						
		Gravel				Sparse to none
Sediment Traps						
Compaction	Fail					Lack of stabilization/compaction/insufficient BMPs
		Ditches				

Comment: [Lack of stabilization/compaction/insufficient BMP's on location](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Inspected Facilities for corrective actions & also refer to Stormwater for comments	smelserw	06/11/2025
Split pad/remote location - Shared facilities with the HMU 10-7 (F10W) location # 334893		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404237680	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7092064
708906717	Inspection/Audit 708906716 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7092062
708906718	Inspection/Audit 708906716 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7092063