

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2025

Submitted Date:

06/12/2025

Document Number:

708906723

**FIELD INSPECTION FORM**

Loc ID 334921 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 25 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
QB Energy		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264836	WELL	PR	10/01/2023	GW	045-08945	HMU 10-1B (A10WB)	PR
264838	WELL	PR	10/01/2023	GW	045-08948	HMU 10-2B (A10WB)	PR
264839	WELL	PR	08/15/2003	GW	045-08949	HMU 10-2D (A10WB)	PR
264877	WELL	PR	08/02/2003	GW	045-08954	ROSE RANCH 10-8B (A10WB)	PR
265104	WELL	PR	08/15/2003	GW	045-08946	HMU 3-15D (A10WB)	PR

**General Comment:**

CECMC Inspection/Audit Report Summary  
On 06/11/2025 at approximately 13:03 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection/audit at QB ENERGY OPERATING LLC HMU 10-1B (A10WB) Pad  
Location # 334921 in Garfield County Colorado.  
Location is within High Priority/Density/Black Bear Habitat areas.  
While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Inspected Facilities - Multiple wells lack wellbore diagrams/not in compliance with CECMC rules with a CA date of 07/12/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
This is a summary of inspection/audit report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Signs at separators		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	5 marked deadman 1 unmarked deadman - please refer to photo log All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:		Tank equipped with telemetry				
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent				
Comment:		Centralized containment				
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		,	
Comment:		Tanks equipped with telemetry				
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent				
Comment:		Centralized containment				
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities			
Facility ID: 264836	Type: WELL	API Number: 045-08945	Status: PR
<b>Producing Well</b>			
Comment:	Producing, well on plunger lift Well lacks wellbore diagram/not in compliance with CECMC Rule 420 Additionally the HMU 10-2D (A10WB) & ROSE RANCH 10-8B (A10WB) wells also lack wellbore diagrams/not in compliance with CECMC Rule 420		
Corrective Action:	Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17	Date:	07/12/2025
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 264838	Type: WELL	API Number: 045-08948	Status: PR
<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 264839	Type: WELL	API Number: 045-08949	Status: PR
<b>Producing Well</b>			
Comment:	Producing, well on plunger lift Well lacks wellbore diagram/not in compliance with CECMC Rule 420		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 264877	Type: WELL	API Number: 045-08954	Status: PR
<b>Producing Well</b>			
Comment:	Producing, well on plunger lift Well lacks wellbore diagram/not in compliance with CECMC Rule 420		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			
Facility ID: 265104	Type: WELL	API Number: 045-08946	Status: PR
<b>Producing Well</b>			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12			

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams						
		Ditches				
Rip Rap						
Ditches						
Gravel						Sparse to none in most areas
		Culverts				
		Gravel				Sparse to none
Berms						
		Compaction				Light compaction in some sections
Compaction						Light compaction in some areas

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Inspected Facilities for corrective actions &amp; also refer to Equipment for comments.</a>	smelserw	06/12/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404239260	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093645">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093645</a>
708906724	Inspection/Audit 708906723 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093643">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093643</a>
708906725	Inspection/Audit 708906723 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093644">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093644</a>