

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2025

Submitted Date:

06/19/2025

Document Number:

707801677

FIELD INSPECTION FORM

Loc ID 415116 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

23 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415094	WELL	PR	11/11/2010	GW	045-18965	GGU FED 42C-32-691	PR
415098	WELL	PR	07/01/2018	GW	045-18967	FEDERAL 22B-33-691	PR
415101	WELL	PR	08/18/2010	GW	045-18969	GGU FED 12B-33-691	PR
415112	WELL	PR	07/21/2010	GW	045-18974	GGU FED 43C-32-691	PR
415115	WELL	PR	10/01/2018	GW	045-18976	FEDERAL 22A-33-691	PR
415117	WELL	PR	07/21/2010	GW	045-18977	GGU FED 43D-32-691	PR
415119	WELL	PR	11/11/2010	GW	045-18979	GGU FED 42B-32-691	PR
415123	WELL	PR	07/21/2010	GW	045-18981	GGU FED 43B-32-691	PR
415134	WELL	PR	07/21/2010	GW	045-18986	GGU FED 43A-32-691	PR
415135	WELL	PR	09/01/2020	GW	045-18987	FEDERAL 22C-33-691	PR
415137	WELL	PR	08/17/2010	GW	045-18988	GGU FED 12A-33-691	PR
415138	WELL	PR	11/01/2018	GW	045-18989	GGU FED 12C-33-691	PR
415139	WELL	PR	10/01/2018	GW	045-18990	GGU FED 12D-33-691	PR
415141	WELL	PR	11/08/2010	GW	045-18991	GGU FED 42D-32-691	PR
415142	WELL	PR	07/01/2018	GW	045-18992	GGU FED 42A-32-691	PR
415143	WELL	PR	09/22/2010	GW	045-18993	GGU FED 41A-32-691	PR
415144	WELL	PR	05/01/2023	GW	045-18994	FEDERAL 22D-33-691	PR

General Comment:

CECMC Inspection Report Summary

On Wednesday 6/18/2025, I, Inspector Scott Ramsey, conducted a follow up inspection/audit at TEP MDP 4, at Location # 415116 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.

During this inspection the following compliance issues were observed:

1. Unused equipment (old B/H tank) pumper told me they were all disconnected.
Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (old B/H tank) pumper told me they were all disconnected.		
Corrective Action:	Remove stored equipment, put into service or provide proper documentation to keep on location.	Date:	08/01/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:			corrective date
Ancillary equipment	# 3		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 17		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 17		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 17		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 17		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 15		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	500 BBLs	HEATED STEEL AST		,
Comment:	2 tanks arer not heated				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	415094	Type:	WELL	API Number:	045-18965	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	415098	Type:	WELL	API Number:	045-18967	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	415101	Type:	WELL	API Number:	045-18969	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	415112	Type:	WELL	API Number:	045-18974	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	415115	Type:	WELL	API Number:	045-18976	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	415117	Type:	WELL	API Number:	045-18977	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	415119	Type:	WELL	API Number:	045-18979	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	415123	Type:	WELL	API Number:	045-18981	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415134 Type: WELL API Number: 045-18986 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415135 Type: WELL API Number: 045-18987 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415137 Type: WELL API Number: 045-18988 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415138 Type: WELL API Number: 045-18989 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415139 Type: WELL API Number: 045-18990 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415141 Type: WELL API Number: 045-18991 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 415142 Type: WELL API Number: 045-18992 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

Corrective Action:		Date:	
--------------------	--	-------	--

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	415143	Type:	WELL	API Number:	045-18993	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	415144	Type:	WELL	API Number:	045-18994	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	Producing	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Ditches						
Gravel						Sparse to none in most areas
		Culverts				
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801683	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7104240