

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2025

Submitted Date:

06/12/2025

Document Number:

719200005**FIELD INSPECTION FORM**Loc ID 334786 Inspector Name: Gaasche, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10844Name of Operator: QB ENERGY OPERATING LLCAddress: 1001 17TH STREET SUITE 1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, "		ecmc.inspections@qb-energy.com	All Inspections
, COGCC		aaron.trujillo@state.co.us	Western Reclamation Work Lead

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
334786	LOCATION	AC			-	COUEY-67S92W 8NWNE	RI

General Comment:

On 05/30/2025, NW Reclamation Specialist Emily Gaasche and Western Reclamation Work Lead Aaron Trujillo conducted an interim reclamation and stormwater inspection at the Couey-67S92W 8NWNE Location in Garfield County, Colorado.

While at the Location, an audible hissing noise was heard coming from the separator associated with well # 045-07527. The inspector Trujillo called Gas Control and notified them of the noise at the time of the inspection (1-800-791-7691).

This Location is within or in close proximity to: CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area.

The following compliance issues were observed during this inspection:

- Undesireable plant species
- Unused equipment on Location

Refer to the Location and Reclamation sections of this report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Signage present at the location entrance.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Signage present at separators.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signage does not comply with current 605 requirements.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615 / 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	A non-functional wattle was observed near the northern interim areas of the Location. Removal is advised.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	#		
Comment:	A flowline riser was observed between separator equipment on the western pad of the Location. Riser is associated with abandoned equipment and has not been properly cut, capped and removed.		

Corrective Action:	Comply with 1004.a and remove riser equipment.		Date:	07/02/2025
Type: Horizontal Heated Separator	#			
Comment:	An audible hiss was detected at the separator associated with well # 045-07527. Inspector contacted Gas Control at the time of the inspection to notify them of a potential leak.			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Comment:	Liner of secondary containment appears to be aging and may need replaced soon.				
Corrective Action:					Date:

Venting:

Yes/No				
Comment:				
Corrective Action:			Date:	

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	334786	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

Anchors were not observed at the time of inspection.

1003b. Area no longer in use? Pass Production areas stabilized ? In
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In
Production areas have been stabilized? In Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? F

Comment Areas of the area not necessary for production have been reduced, and reclamation is in process.

Weeds such as houndstongue, cheatgrass, field bindweed, redstem fillaree, and tamarisk were observed to have established throughout the location. Additional weed management efforts are required.

Corrective Action Comply to Rule 1003.f and 606.c.; Oil and Gas Locations will be kept free of all undesirable plant species.

Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:						Date _____	
Corrective Action:							
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>			
Storm Water:							
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment	
Comment:		BMP's to stabilize the Location, as well as to minimize erosion, degradation and vehicle tracking shows signs of disrepair. Vehicle tracking/rutting is becoming evident on the eastern pad of the Location. Maintenance is advised.					Date: _____
Corrective Action:							
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT							

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404242249	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097081
719200015	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097078