

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2025

Submitted Date:

06/16/2025

Document Number:

717100255

FIELD INSPECTION FORMLoc ID 463256 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10634

Name of Operator: P O & G OPERATING LLC

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Nash, Charlotte	281.543.3606	charlotte_nash@pogresources.com	Production and Regulatory
Sanchez, Chris		chris.sanchez@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Hudson, Glenn	713-589-8186	glenn_hudson@pogresources.com	All Inspections
RANDO, CHRIS		christopher_rando@pogresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488988	SPILL OR RELEASE	CL	10/14/2024		-	Lowe B-2 TB (Lowe-611S46W 14NWNE)	EI

General Comment:

ECMC Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 488988 and Remediation Project # 34658. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill Name: Lowe B-2 TB (Lowe-611S46W 14NWNE)

Spill ID: 488988

Remediation Project #: 34658

Facility ID: 463256

Reported Date of Discovery: 05/09/2024

Date of Inspection: 05/30/2025

Weather: Sunny, 77°F

Spill is located within or adjacent to:

-Wetlands (Riverine, ~260 ft west)

Current site status:

-Multiple trenches/small excavations remain open.

-Areas of ground surface subsidence were visible.

-Fence posts with pieces of plastic tape have been installed at the excavations/trenches and depressions; no fencing was visible.

-Segments of multiple of lines and uncapped risers were visible on location.

-Multiple pin flags are visible throughout the location and appear to have been placed adjacent to areas of ground disturbance.

-Weeds are visible on location.

See attached corrective actions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds are visible on location.		
Corrective Action:	Comply with Rule 606.		Date: 06/23/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	Fence posts with pieces of plastic tape have been installed at the excavations/trenches and depressions; no fencing was visible.		
Corrective Action:	Secure access to excavation in accordance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.		Date: 06/30/2025

Equipment:

Type:	#		corrective date
Comment:	Improper abandonment of flowline or crude oil transfer line per 1105.e.(4). Segments of multiple of lines and uncapped risers were visible on location.		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.e.(4).		Date: 07/16/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	488988	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project # 34658 was created for decommissioning of the Lowe B-2 TB (Lowe-611S46W 14NWNE) facility. Multiple trenches/small excavations remain open. Areas of ground surface subsidence were visible. Multiple pin flags are visible throughout the location and appear to have been placed adjacent to areas of ground disturbance. Quarterly reporting is required under Remediation Project # 34658; the last Form 27 for this project was submitted 02/14/2024 (Document Number 403685171).

Corrective Action: Operator shall submit delinquent form(s) for this project.

Date: 06/30/2025

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404242162	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097023
717100261	ECMC Photo Log - Lowe B-2 TB (Lowe-611S46W 14NWNE) - 05.30.2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7097016