

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2025

Submitted Date:

06/24/2025

Document Number:

710500566**FIELD INSPECTION FORM**Loc ID 320975 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	BACA Inspections
Serna, Abe		abe.serna@state.co.us	
Crane, Shaun	719-353-2526	cimbaca.production.services@gmail.com	
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205636	WELL	PR	04/01/2023	GW	009-06047	STATE OF COLORADO 1-15	EI
320975	LOCATION	AC			-	STATE OF COLORADO-631S44W 15SENW	EI

General Comment:This is an Environmental Inspection for the State of Colorado 1-15 well location located in Baca County, Colorado.

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Well Placards on site are illegible, Previous Corrective Actions (CA's), and comments shall apply		
Corrective Action:		Date:	
Type	OTHER		
Comment:	H2s placards have fallen and need reposted on the site.		
Corrective Action:	Comply with Rule 605.d.(4).	Date:	06/30/2025

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	At the time of inspection the tank on location was not in use and appears to be Unused Equipment. Not in use is spray painted on the tank wall.		
Corrective Action:	Comply with Rule 606	Date:	07/24/2025

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	The fencing surrounding the pump jack and equipment has been repaired.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:	At the time of inspection, a Chart Recorder was noted on the gas flowline downstream from the wellhead.		
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:	At the time of inspection, a gas gathering line was noted running from the wellhead in an easterly direction. There are two corrugated valve boxes located east of the well location, which appear to be related to Location ID 320975. ECMC Staff was not able to locate a Form 44 for the related Off Location Flowline/Gas Gathering Line. In Addition, a gas meter was noted adjacent to the corrugated valve boxes.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

