

# Final Reclamation and Stormwater Inspection

May 13, 2025

Operator: ENERGY SEARCH CO ADBA ENERGY SEARCH CO  
INC - 27635

Location ID: 319844

Well Name: GINTHER #2

Inspection Document #: 718600595

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GINTHER #2  
Location ID: 319844



**Photo 1.** Looking east across the former well location. No oil and gas equipment remains on location. Location is now a drainage basin for housing development.



**Photo 2.** Looking at the southeast part of the well location from center. Vegetation coverage appears to be 80% of the reference vegetation.



Inspection Photos  
Location Name: GINTHER #2  
Location ID: 319844



**Photo 3.** Looking southwest across the well location from center. See photo 2 comments.



**Photo 4.** Looking west across the former tank battery. Tank battery now appears to be residential development. No oil and gas equipment remains.

Inspection Photos  
Location Name: GINTHER #2  
Location ID: 319844



**Photo 5.** Looking west from the center of tank battery. See photo 4 comments.



**Photo 6.** Looking west along the south side of the tank battery, on the south side of residential fence.



Inspection Photos  
Location Name: GINTHER #2  
Location ID: 319844



**Photo 7.** Two monitoring wells are present south of the fence (red circles). It does not appear these are associated with the remediation project.



**Photo 8.** Monitoring well.



Inspection Photos  
Location Name: GINTHER #2  
Location ID: 319844



**Photo 9.** The last and most recent groundwater monitoring report (Doc 2528946) included this figure of monitoring wells associated with remediation project 10065



Inspection Photos  
Location Name: GINTHER #2  
Location ID: 319844



**Photo 10.** Google earth imagery taken 2015 showing tank battery equipment (red dot), approximate sampling well locations (green pins), approximate existing well locations (blue dots).



**Photo 11.** Google earth aerial imagery with the same markers as photo 10. It does not appear that the existing monitoring wells are associated with the remediation project.