

NININGER 11-1-1645

Photo Log

Inspection Comment: No fencing was visible surrounding the excavation southeast of the former wellhead.

Corrective Action Requested: Secure access to excavation in accordance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.

Description of Compliance: Excavation area secured with fencing per Rule 913.b.(5)



NININGER 11-1-1645

Photo Log

Inspection Comment: An unmarked soil stockpile was visible next to a small excavation southeast of the former wellhead. No stormwater BMPs or liner was visible at the stockpile.

Corrective Action Requested: Operator shall comply with Rule 913.b.(5).B.iv. and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil.

Description of Compliance:

