

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/27/2025

Submitted Date:

06/27/2025

Document Number:

698707681

FIELD INSPECTION FORM

Loc ID 308375 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,	719-846-7898	cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270298	WELL	SI	04/01/2025	CBM	071-07940	Anderson 42-18V	SI
286820	WELL	PR	03/01/2017	CBM	071-08991	Anderson 42-18R	PR

General Comment:

[Wellsite Inspection](#)

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Sign on meter house		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

							corrective date
Type: Prime Mover	# 1						
Comment:							
Corrective Action:							Date:
Type: Deadman # & Marked	# 4						
Comment:							
Corrective Action:							Date:
Type: Bradenhead	# 2						
Comment:							
Corrective Action:							Date:
Type: Progressive Cavity	# 1						
Comment:							
Corrective Action:							Date:
Type: Pump Jack	# 1						
Comment:							
Corrective Action:							Date:
Type: Vertical Separator	# 2						
Comment:							
Corrective Action:							Date:
Type: Gas Meter Run	# 2						
Comment:							
Corrective Action:							Date:
Type: Ancillary equipment	# 2						
Comment:							

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 270298 Type: WELL API Number: 071-07940 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI
Flowline valve closed

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/22/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Form 4 on file

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286820 Type: WELL API Number: 071-08991 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 10/22/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Form 4 on file

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>Routine Inspection</u>	sernaa	06/27/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698707682	Photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7117903