

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/25/2025

Submitted Date:

06/27/2025

Document Number:

707604005

FIELD INSPECTION FORM

Loc ID 332935 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|-----------------|
| | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 287480 | WELL | TA | 05/04/2020 | GW | 123-24341 | CECIL USX A 1-10 | TA |

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.515001 / -104.497637

Abandoned Centralized Battery formerly served 11 Location IDs (332935, 302408, 302409, 302410, 302413, 302414, 302415, 306355, 310486, 310487, 333048). (Well(s): 4: Temporarily Abandoned | TA; 9: Plugged & Abandoned | PA).

Reference (Associated Well(s) Inspections):
A.) Field Inspection Report doc. #707604005 and/or Location ID #332935 for TA Well(s) info.
B.) Field Inspection Report doc. #707604007 and/or Location ID #302413 for TA Well(s) info.
C.) Field Inspection Report doc. #707604009 and/or Location ID #302414 for TA Well(s) info.
D.) Field Inspection Report doc. #707604011 and/or Location ID #310487 for TA Well(s) info.
E.) Field Inspection Report doc. #707604013 and/or Location ID #302408 for PA Well(s) info.
F.) Field Inspection Report doc. #707604015 and/or Location ID #302410 for PA Well(s) info.
G.) Field Inspection Report doc. #707604017 and/or Location ID #306355 for PA Well(s) info.
H.) Field Inspection Report doc. #707604019 and/or Location ID #310486 for PA Well(s) info.
I.) Field Inspection Report doc. #707604021 and/or Location ID #333048 for PA Well(s) info.
J.) Field Inspection Report doc. #707604023 and/or Location ID #333048 for PA Well(s) info.

| Location | | | |
|--|--|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | CORRECTIVE GUIDANCE Item(s): 1.) Emergency contact number peeling. Post legible emergency contact number. Refer to Rule 605.g for guidance. See photo #1. | | |
| Corrective Action: | | | Date: |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | CORRECTIVE GUIDANCE Item(s): 2.) Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. See photo #1. | | |
| Corrective Action: | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Plunger Lift | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears plumbed to surface. | | |
| Corrective Action: | | | Date: |
| Venting: | | | |

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 287480 Type: WELL API Number: 123-24341 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
Locked-Out, Tagged-Out | LOTO.
Yellow LTSI, OOSLAT tag(s) posted at well.
ECMC records last production: 2/2017.

Form 4 on file. TA date: 12/13/2018. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 01/10/2015. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 08/23/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>CECMC Inspection Report Synopsis:</p> <p>On WED 06/25/2025 at approximately 15:44 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: CECIL USX A-66N64W/1NWSE Location ID: 332935 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.515001 / -104.497637</p> <p>CORRECTIVE GUIDANCE Item(s): 1.) See "Signs/Marker" section on page 2 of this report. 2.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p> | evinsb | 06/27/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 707604006 | Inspection photo(s) | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7118363 |