

Harker Ranch Morrow Unit (HRMU 7)

Well & Location

Photo Log

Inspection Comment: There is unused equipment stored at the east side of the location which must be removed.

Corrective Action Requested: Comply with Rule 606

Description of Compliance: All unused equipment has been removed from location.

