

WELL NAME: ULIBARRI 32-6 R, API #: 071-09006, INSP. # 716301186



PHOTO 1: WELL SIGN







**PHOTO 2: LOCATION.**







**PHOTO 3: WELLHEAD AND EQUIPMENT.**







**PHOTO 4: WEEDS OVERGROWN AROUND LOCATION. WEEDS INSIDE ANCHORS NEED TO BE MAINTAINED PER RULE 606 CA DATE 7-12-2025.**







**PHOTO 5: DEAD WEEDS AROUND LOCATION ARE A FIRE HAZARD. CUT AND REMOVE DEAD WEEDS PER RULE 606. CA DATE 7-12-2025.**







**PHOTO 6: THERE IS AN AREA OF IMPACED SOILS AROUND THE PRIME MOVER ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D CA DATE 7-12-2025.**







**PHOTO 7: OILY WASTE IN PRIME MOVER ENGINE SKID. DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO REMOVE OILY WASTE CA DATE 7-12-2025.**







**PHOTO 8: ANCHOR MARKER IS DOWN ON THE NORTH EAST ANCHOR FROM WELLHEAD. Install proper guy line markers per Rule 1003.a. CA DATE 7-2-2025 DUE TO GROWNING SEASON FARM HAND WAS CUTTING AT TIME OF INSPECTION.**