

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	PHOTO 5: DEAD WEEDS AROUND LOCATION ARE A FIRE HAZARD.		
Corrective Action:	CUT AND REMOVE DEAD WEEDS PER RULE 606.	Date:	07/12/2025
Type	OTHER		
Comment:	PHOTO 6: THERE IS AN AREA OF IMPACED SOILS AROUND THE PRIME MOVER ENGINE SKID.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D	Date:	07/12/2025
Type	WEEDS		
Comment:	PHOTO 4: WEEDS OVERGROWN AROUND LOCATION.		
Corrective Action:	WEEDS INSIDE ANCHORS NEED TO BE MAINTAINED PER RULE 606.	Date:	07/12/2025

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. METER WILL NEED CALIBRATED BEFORE THE END OF THIS MONTH TO REMAIN IN COMPLIANCE.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 7		
Comment:	PHOTO 8: ANCHOR MARKER IS DOWN ON THE NORTH EAST ANCHOR FROM WELLHEAD.		
Corrective Action:	Install proper guy line markers per Rule 1003.a. CA DATE 7-2-2025 DUE TO GROWNING SEASON FARM HAND WAS CUTTING AT TIME OF INSPECTION.		Date: <u>07/02/2025</u>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 287035 Type: WELL API Number: 071-09006 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: WELL LAST PRODUCED JULY 2024.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/19/2011 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 ON FILE

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [PHOTO 7: OILY WASTE IN PRIME MOVER ENGINE SKID.](#)

Corrective Action: **DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. 24 HOURS TO REMOVE OILY WASTE**

Date: 07/12/2025

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716301187	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7124310