

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/01/2025

Submitted Date:

07/02/2025

Document Number:

719000277

FIELD INSPECTION FORM

Loc ID 325300 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Kosola, Jason		jason.kosola@state.co.us	

General Comment:

Inspection Report Summary
On 7/1/25 I Inspector Charles Garcia conducted an on-site follow up inspection.DOCUMENT #719000077 CA SQUIRES #4, MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUNDPUMPJACK rule 1002.f
Location: SQUIRES #4, SQUIRES #1
Operator:HILCORP ENERGY COMPANY
#1 API#: 067-06118
#4 API#: 067-09762
County: LaPlata

Location

Overall Good:

Emergency Contact Number: _____

Comment: _____

Corrective Action: _____ Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	OIL SOAKED RAGS, DIAPERS,AND UNUSED EQUIPMENT UNDERNEATH AND AROUND PRIME MOVER SEE LOCATION PICTURES		
Corrective Action:	REMOVE DEBRIS AND UNUSED EQUIPMENT PER RULE 605	Date:	07/09/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type			corrective date
Pump Jack	# 2		
Comment:	DRIVE BELT ON SQUIRES #1 BROKEN ON RIGHT SIDE SEELOCATION PICTURES		
Corrective Action:		Date:	
Prime Mover	# 2		
Comment:	INSPECTION DOCUMENT #71900077 CA GAS ENGINE FOR PRIME MOVER ON THE SQUIRES #4 LEAKING OIL STARTING TO IMPACT SOIL AROUND PUMP JACK. FIR DOCUMENT #404250985 SUBMITTED ON 6/23/25 IMPACTED SOIL DID NOT APPEAR TO BE REMOVED. AND WAS COVERED WITH APPROXIMATELY 1 IN OF GRAVEL. CLEAN UP NOT APPROVED BY ECMC. PRIME MOVER GAS ENGINE NOT RUNING AT TIME OF FOLLOW UP INSPECTION.		
Corrective Action:	MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND PUMPJACK rule 1002.f	Date:	05/23/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

ECMC Comments

Comment	User	Date
IMPACTED SOIL DID NOT APPEAR TO BE REMOVED. AND WAS COVERED WITH APPROXIMATELY 1 IN OF GRAVEL.OIL SOAKED RAGS, DIAPERS,AND UNUSED EQUIPMENT UNDERNEATH AND AROUND PRIME MOVER SEE LOCATION PICTURES.	garciacr1	07/01/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000281	LOCATION FOLLOW UP PICTURES	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7126135
719000284	FIR DOCUMENT 404250985	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7126136