

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2025

Submitted Date:

07/07/2025

Document Number:

713400901

FIELD INSPECTION FORMLoc ID 334528 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

28 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	
Longworth, Mike		mike.longworth@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285683	WELL	PR	11/03/2015	GW	077-09095	CURRIER 26-15	PR
285684	WELL	PR	03/01/2023	GW	077-09096	CURRIER 26-16	PR
285685	WELL	SI	02/01/2024	GW	077-09097	CURRIER 26-14	PA
285687	WELL	PR	03/01/2017	GW	077-09098	CURRIER 26-10	PR
285688	WELL	PR	05/30/2012	GW	077-09099	CURRIER 26-9C	PR
285692	WELL	PR	04/01/2023	GW	077-09100	CURRIER 35-2	PR
285694	WELL	PR	01/01/2011	GW	077-09101	CURRIER 35-1	PR
285696	WELL	PR	06/01/2024	GW	077-09102	CURRIER 25-13	PR
285699	WELL	PR	06/01/2024	GW	077-09103	CURRIER 35-3	PR
285702	WELL	PR	01/01/2011	GW	077-09104	CURRIER 36-4	PR

General Comment:

CECMC Inspection/Audit Report Summary

On 07/1/2025 at approximately 13:57 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at LARAMIE ENERGY LLC Currier 26-15 PAD at Location ID #334528 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Housekeeping - Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard with a CA date of 07/14/2025
2. Equipment - Multiple unused flowlines do not comply with CECMC 600 & 1100 series rules with a CA date of 07/14/2025
3. Equipment - Multiple holes in separator buildings open to wildlife/available for entry by wildlife with a CA date of 07/14/2025
4. Equipment - PRV vent line does not comply with CECMC pressure safety device rules with a CA date of 07/14/2025
5. Tanks and Berms - Multiple holes in both secondary containments liners/liners needs maintenance with a CA date of 07/27/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-891-6191/911

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard		
Corrective Action:	Oil and Gas Locations will be kept free of all Undesirable Plant Species	Date:	07/14/2025

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 6		
Comment:	Multiple holes in separator buildings open to wildlife/available for entry by wildlife		

Corrective Action:	Comply with CECMC wildlife rules		Date:	07/14/2025
Type: Bradenhead	# 9			
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible			
Corrective Action:			Date:	
Type: Pig Station	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 10			
Comment:				
Corrective Action:			Date:	
Type: Other	# 10			
Comment:	Multiple unused flowlines do not comply with CECMC 600 & 1100 series rules			
Corrective Action:	Comply with CECMC 600 & 1100 series rules		Date:	07/14/2025
Type: Other	# 1			
Comment:	PRV vent line does not comply with CECMC pressure safety device rules			
Corrective Action:	Comply with CECMC pressure safety device rules		Date:	07/14/2025
Type: Plunger Lift	# 9			
Comment:	All wells on plunger lift			
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 10			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 4			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:	1 Tank equipped with telemetry					
Corrective Action:					Date:	

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				

Comment:		Multiple holes in secondary containment liner/liner needs maintenance. The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.						
		Separate centralized containment						
Corrective Action:							Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS			
CONDENSATE	3	300 BBLs	STEEL AST		,			
Comment:		Tank equipped with telemetry						
Corrective Action:							Date:	
<u>Paint</u>								
Condition	Inadequate							
Other (Content)								
Other (Capacity)								
Other (Type)								
<u>Berms</u>								
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance				
Metal	Inadequate	Walls Insufficient	Base Insufficient	Inadequate				
Comment:		Multiple holes in secondary containment liner/liner needs maintenance/liner lacks integrity						
		Centralized containment						
Corrective Action:							Date:	07/27/2025
The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.								
<u>Venting:</u>								
Yes/No	NO							
Comment:								
Corrective Action:								Date:
<u>Flaring:</u>								
Type								
Comment:								
Corrective Action:								Date:

Inspected Facilities

Facility ID: 285683 Type: WELL API Number: 077-09095 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285684 Type: WELL API Number: 077-09096 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285685 Type: WELL API Number: 077-09097 Status: SI Insp. Status: PA

Idle Well

Purpose: ☐ Shut In

☐ Temporarily Abandoned

Reminder: _____

Comment: Well P&A refer to document number 403620502

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285687 Type: WELL API Number: 077-09098 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285688 Type: WELL API Number: 077-09099 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285692 Type: WELL API Number: 077-09100 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 285694 Type: WELL API Number: 077-09101 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	285696	Type:	WELL	API Number:	077-09102	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	285699	Type:	WELL	API Number:	077-09103	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	285702	Type:	WELL	API Number:	077-09104	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Date Run: 7/7/2025 Doc [#713400901]Page 7 of 8

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
		Culverts				
		Ditches				
Ditches						
Berms						
Gravel						Sparse
		Berms				
Sediment Traps						
		Compaction				
Compaction						
		Gravel				Sparse

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping, Equipment & Tanks and Berms for corrective actions.	popejoyd	07/07/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400902	713400901 Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7130436