

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/07/2025

Submitted Date:

07/08/2025

Document Number:

717300396

FIELD INSPECTION FORM

Loc ID 332548 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247558	WELL	SI	09/01/2020	GW	123-15355	TUTTLE INVESTMENT CO.UNIT 1	PA
332548	LOCATION	AC			-	TUTTLE INVESTMENT CO.UNIT-63N66W 8NENW	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 247558 Type: WELL API Number: 123-15355 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 332548 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Tuttle Investment CU 1); ECMC form 42 notice of start of plugging operations doc #404067742 received on 01/23/2025. Wellhead flowline has been removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed doc #404194381 received 05/07/2025 (OL facility FL's removed). No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	07/08/2025
As outlined on ECMC form 19 spill report Doc #404266304 received on 07/03/2025: While conducting wellhead plugging and abandonment and flowline removal activities at the Tuttle Invest Co UN1 wellhead, historically impacted soil was discovered at the separator riser. The volume of the release is unknown. The flowline has been permanently removed.	maclarej	07/08/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300397	Excavation at PA well; Signage	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7132588
717300398	Excavation at facility; OOS GMR	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7132589