

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2025

Submitted Date:

07/02/2025

Document Number:

719000277**FIELD INSPECTION FORM**Loc ID 325300 Inspector Name: GARCIA, CHARLES On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Kosola, Jason		jason.kosola@state.co.us	

**General Comment:**Inspection Report SummaryOn 7/1/25 I Inspector Charles Garciaconducted an on-site follow up inspection.DOCUMENT #719000077 CA SQUIRES #4, MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUNDPUMPJACK rule 1002.fLocation: SQUIRES #4, SQUIRES #1Operator:HILCORP ENERGY COMPANY#1 API#: 067-06118#4 API#: 067-09762County: LaPlata

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	DEBRIS		
Comment:	OIL SOAKED RAGS, DIAPERS,AND UNUSED EQUIPMENT UNDERNEATH AND AROUND PRIME MOVER SEE LOCATION PICTURES		
Corrective Action:	REMOVE DEBRIS AND UNUSED EQUIPMENT PER RULE 605		Date: 07/09/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Prime Mover	# 2		corrective date
Comment:	INSPECTION DOCUMENT #719000077 CA GAS ENGINE FOR PRIME MOVER ON THE SQUIRES #4 LEAKING OIL STARTING TO IMPACT SOIL AROUND PUMP JACK. FIR DOCUMENT #404250985 SUBMITTED ON 6/23/25 IMPACTED SOIL DID NOT APPEAR TO BE REMOVED. AND WAS COVERED WITH APPROXIMATELY 1 IN OF GRAVEL. CLEAN UP NOT APPROVED BY ECMC. PRIME MOVER GAS ENGINE NOT RUNING AT TIME OF FOLLOW UP INSPECTION.		
Corrective Action:	MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND PUMPJACK rule 1002.f		Date: 05/23/2025
Type: Pump Jack	# 2		
Comment:	DRIVE BELT ON SQUIRES #1 BROKEN ON RIGHT SIDE SEELOCATION PICTURES		
Corrective Action:			Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**ECMC Comments**

Comment	User	Date
IMPACTED SOIL DID NOT APPEAR TO BE REMOVED. AND WAS COVERED WITH APPROXIMATELY 1 IN OF GRAVEL.OIL SOAKED RAGS, DIAPERS,AND UNUSED EQUIPMENT UNDERNEATH AND AROUND PRIME MOVER SEE LOCATION PICTURES	garciacr1	07/01/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404266350	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7126138">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7126138</a>
719000281	LOCATION FOLLOW UP PICTURES	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7126135">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7126135</a>
719000284	FIR DOCUMENT 404250985	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7126136">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7126136</a>