

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/07/2025

Submitted Date:

07/11/2025

Document Number:

708906833

**FIELD INSPECTION FORM**

Loc ID: 335136  
Inspector Name: Smelser, Wayne  
On-Site Inspection:   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 17 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
TEP		COGCCInspectionReports@terraep.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211215	WELL	PR	12/19/1995	GW	045-06974	FEDERAL RMV-33-20	PR
265048	WELL	PR	01/07/2004	OW	045-08978	FEDERAL RWF 334-17	PR
265049	WELL	PR	09/23/2002	OW	045-08979	FEDERAL RWF 344-17	PR
279142	WELL	PR	08/03/2005	GW	045-11004	GARFIELD COUNTY RWF 541-20	PR
279146	WELL	PR	08/03/2005	GW	045-11008	GARFIELD COUNTY RWF 441-20	PR

**General Comment:**

**CECMC Inspection/Audit Report Summary**

On 07/07/2025 at approximately 15:23 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC FEDERAL RMV 33-20 pad. Location # 335136 in Garfield County Colorado. Location is within High Priority/Density Habitat areas. Location is approximately 207 yards from creek/drainage that contributes to the Colorado River. While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Inspected Facilities - FEDERAL RMV 33-20 well shows possible lack of mechanical integrity with a CA date of 10/15/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.

Remote location/split pad - Wellheads only, tank battery & separators located on the CLOUGH 135 pad, location # 322438

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Plunger Lift	# 5		corrective date
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:	RMV 33-20 & RWF 334-17 wells have Taylor plugs on bradenheads, bradenhead valves are accessible.  Remaining 3 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:			Date:
<b>Venting:</b>			

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 211215 Type: WELL API Number: 045-06974 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/15/2025 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 127 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: No differential pressure between SC & PC at start of most recent BH test & additionally the well's bradenhead pressure is 38.9% of the TVD in feet of the surface casing shoe expressed in psig.

Well shows possible lack of mechanical integrity/possibly not in compliance with CECMC Rule 417

Additionally operator is not in compliance with CECMC Rule 419 b. (4)

Corrective Action: Comply with CECMC 400 series rules - Demonstrate to the satisfaction of the CECMC Engineering Group that the well has mechanical integrity & is in compliance with CECMC Rule 417 &/or repair or PA. Additionally contact CECMC Engineering Group to discuss observed compliance issues related to CECMC 400 series rules referenced above.

Date: 10/15/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 265048 Type: WELL API Number: 045-08978 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 265049 Type: WELL API Number: 045-08979 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 279142 Type: WELL API Number: 045-11004 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 279146 Type: WELL API Number: 045-11008 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing, well on plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				Sparse to none
		Ditches				
Compaction						Light compaction in some areas
		Culverts				
Gravel						Sparse to none

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>Please refer to Inspected Facilities for corrective actions.</p> <p>Location is inside the Garfield County Landfill.</p> <p>Remote location/split pad - Wellheads only, tank battery &amp; separators located on the CLOUGH 135 pad, location # 322438</p>	smelserw	07/11/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708906834	Inspection/Audit 708906833 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138443">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138443</a>
708906835	Inspection/Audit 708906833 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138444">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7138444</a>