

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 88 From entrance to location



Photo # 89 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 90 Location



Photo # 91 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 92 Location



Photo # 93 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 94 Location



Photo # 95 Open ended load line

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 96 Unmarked deadman



Photo # 97 Same unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 98 Same unmarked deadman



Photo # 99 Debris

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 100 Unused flowlines lack lockout tagout (OOSLAT)



Photo # 101 Unused flowlines lack lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 102 Hole in liner/liner needs maintenance



Photo # 103 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 104 Holes in liner/liner needs maintenance



Photo # 105 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 106 Hole in liner/liner needs maintenance



Photo # 107 Holes in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442




Photo # 108 Hole in liner/liner needs maintenance



Photo # 109 Hole in liner/liner needs maintenance

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W 10NESW Pad

Location ID: 322442



Photo # 110 Debris



Photo # 111 Tank label starting to peel