

Inspection Photos

06/06/2025

Operator: QB ENERGY OPERATING LLC

#10844

Location ID: 334844

Inspection Doc: 719200023

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334844



Photo 1: Photos taken from the central portion of the Location and provide an overview looking west and north, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334844



Photo 2: Photos taken from the central portion of the Location looking south and east, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334844



Photo 3: Photo taken from the western perimeter of the Location. Damaged, unused wattles are present. Comply with Rule 606.a and remove debris.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334844



Photo 4: Photo taken from the west-central portion of the Location. An unused guy-line anchor is present. Comply with Rule 606.a and remove unused equipment.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334844



Photo 5: Photos taken at the northern and southwest portions of the Location, respectively. Undesireable weeds like plumeless thistle (left) and Russian knapweed (right) are present in the interim areas. Comply with Rule 606.a and remove undesirable plant species.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334844



Photo 6: Photos showing unused pipe equipment near the southwestern fence line. Comply with Rule 606.a and remove unused equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334844



Photo 7: Light sediment tracking was observed throughout the pad. It is recommended that BMPs be maintained to reduce sediment transport off of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334844



Photo 8: An active ground nest, likely a western meadowlark, was observed on the edge of the eastern cut slope, shown in the yellow highlighted area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources