

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2025

Submitted Date:

07/09/2025

Document Number:

707801695

FIELD INSPECTION FORM

Loc ID 336009	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 30 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296450	WELL	PR	03/22/2009	GW	045-16032	JOLLEY 8-213D	PR
296451	WELL	PR	03/17/2009	GW	045-16033	JOLLEY 8-215D	PR
296452	WELL	PR	08/14/2014	GW	045-16034	JOLLEY 8-315D	PR
296453	WELL	PR	05/01/2015	GW	045-16035	JOLLEY 8-313D	PR
424972	WELL	PR	08/01/2015	GW	045-20980	Jolley KP 534-8	PR
424973	WELL	PR	10/01/2020	GW	045-20981	Jolley KP 23-8	PR
424975	WELL	PR	05/31/2012	GW	045-20983	Jolley KP 21-17	PR
424976	WELL	PR	08/23/2012	GW	045-20984	Jolley KP 524-8	PR
424977	WELL	PR	05/02/2012	GW	045-20985	Jolley KP 421-17	PR
424978	WELL	PR	05/29/2012	GW	045-20986	Jolley KP 321-17	PR
424979	WELL	PR	09/20/2012	GW	045-20987	Jolley KP 334-8	PR
424980	WELL	PR	09/20/2012	GW	045-20988	Jolley KP 333-8	PR
424981	WELL	PR	04/30/2012	GW	045-20989	Jolley KP 431-17	PR
424982	WELL	PR	09/20/2012	GW	045-20990	Jolley KP 533-8	PR
424983	WELL	PR	07/31/2012	GW	045-20991	Jolley KP 323-8	PR
424984	WELL	PR	08/23/2012	GW	045-20992	Jolley KP 324-8	PR
424985	WELL	PR	09/20/2012	GW	045-20993	Jolley KP 331-17	PR
424986	WELL	PR	02/28/2013	GW	045-20994	Jolley KP 411-17	PR
424987	WELL	PR	02/28/2013	GW	045-20995	Jolley KP 311-17	PR
424988	WELL	PR	02/21/2013	GW	045-20996	Jolley KP 423-8	PR
424989	WELL	PR	03/21/2013	GW	045-20997	Jolley KP 523-8	PR

424990	WELL	PR	02/28/2013	GW	045-20998	Jolley KP 11-17	PR
426302	WELL	PR	09/20/2012	GW	045-21135	Jolley KP 31-17	PR

General Comment:

CECMC Inspection Report Summary

On Tuesday 7/8/2025, I, Inspector Scott Ramsey, conducted a follow up inspection/audit at TEP KP 24-8, at Location # 336009 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.

C/A's from previous inspection document # 708303834 has been addressed.

During this inspection the following compliance issues were observed:

1. Cut slope lacks stabilization

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:Comment: [911/970-285-9377](tel:9119702859377)

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	Chemical tank in plastic containment		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 20		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:	1 running and metered, 1 LOTO		
Corrective Action:			Date:
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:
Contents	#	Capacity	Type	Tank ID
PRODUCED WATER	5	300 BBLs	STEEL AST	
Comment:	2 tanks are heated			
Corrective Action:				Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:
Contents	#	Capacity	Type	Tank ID
CONDENSATE	6	300 BBLs	HEATED STEEL AST	
Comment:				
Corrective Action:				Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities				
Facility ID:	296450	Type:	WELL	API Number: 045-16032 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296451	Type:	WELL	API Number: 045-16033 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296452	Type:	WELL	API Number: 045-16034 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	296453	Type:	WELL	API Number: 045-16035 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	424972	Type:	WELL	API Number: 045-20980 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	424973	Type:	WELL	API Number: 045-20981 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	424975	Type:	WELL	API Number: 045-20983 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	424976	Type:	WELL	API Number: 045-20984 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424977	Type:	WELL
API Number:	045-20985	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424978	Type:	WELL
API Number:	045-20986	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424979	Type:	WELL
API Number:	045-20987	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424980	Type:	WELL
API Number:	045-20988	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424981	Type:	WELL
API Number:	045-20989	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424982	Type:	WELL
API Number:	045-20990	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424983	Type:	WELL
API Number:	045-20991	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		

Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424984	Type:	WELL
API Number:	045-20992	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424985	Type:	WELL
API Number:	045-20993	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424986	Type:	WELL
API Number:	045-20994	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424987	Type:	WELL
API Number:	045-20995	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424988	Type:	WELL
API Number:	045-20996	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424989	Type:	WELL
API Number:	045-20997	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	424990	Type:	WELL
API Number:	045-20998	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Facility ID:	426302	Type:	WELL	API Number:	045-21135	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
		Culverts				
Gravel						
		Ditches				

Comment:

1. Cut slope lacks stabilization

The cut slope on the location is not stabilized. Portions of the slope appear to be sloughing off, as the cut is almost vertical. The top of the slope appears to be undercutting. Sediment from the slope was observed accumulating at the slope base. Stakes from old waddles still evident.

Corrective Action:

Install, maintain or repair required BMPs

Date: 08/20/2025

Pits:☒ NO SURFACE INDICATION OF PIT**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404273493	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134871
707801701	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134841