

Inspection Photos  
Facility 4 @ UPRR 43 PAN AM AE  
Spill ID 485940/Remediation Project No 34672



Photo 1 – Open excavation. Downed fencing/weeds.

Photo 2 - Open excavation. Downed fencing/weeds.

Inspection Photos  
Facility 4 @ UPRR 43 PAN AM AE  
Spill ID 485940/Remediation Project No 34672



Photo 3 – Open excavation. Downed fencing/weeds.

Photo 4 - Open excavation. Downed fencing/weeds.

Inspection Photos  
Facility 4 @ UPRR 43 PAN AM AE  
Spill ID 485940/Remediation Project No 34672



**Photo 5 – Contaminated soil stockpile. Weeds.**

**Photo 6 - Contaminated soil stockpile. Weeds.**

**Inspection Photos**  
**Facility 4 @ UPRR 43 PAN AM AE**  
**Spill ID 485940/Remediation Project No 34672**



**Photo 7 – Contaminated soil stockpile. Weeds/torn liner.**

**Photo 8 - Contaminated soil stockpile. Soil stockpile overflowing berms. Weeds.**

**Inspection Photos**  
**Facility 4 @ UPRR 43 PAN AM AE**  
**Spill ID 485940/Remediation Project No 34672**



ECMC Environmental Inspection  
40.09407, -104.92458, 1510.4m, 31°  
07/15/2025 02:39:57 PM

**Photo 9 – Contaminated soil stockpile. Soil stockpile overflowing berms. Weeds.**



ECMC Environmental Inspection  
40.09413, -104.92443, 1510.8m, 279°  
07/15/2025 02:40:57 PM

**Photo 10 - Contaminated soil stockpile. Soil stockpile overflowing berms. Weeds.**