

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2025

Submitted Date:

07/17/2025

Document Number:

697011706

**FIELD INSPECTION FORM**

Loc ID 329965 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 52530  
Name of Operator: MAGPIE OPERATING INC  
Address: 2707 SOUTH COUNTY RD 11  
City: LOVELAND State: CO Zip: 80537

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kost, Jody		magpieoil2@yahoo.com	
Fanning, Trisha		tfanning@ardorenvironmental.com	
Warner, Ross		ross.magpieoil@gmail.com	
Donahue, Jessica		jdonahue@ardorenvironmental.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250300	WELL	TA	11/01/2019	GW	123-18103	PETERSON 4	WK

**General Comment:**

This is a well plugging audit.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:		Date:	

**Equipment:**

Type:	Other	#		corrective date
Comment:	Rig, pump and work tank are grounded.			
Corrective Action:				Date:
Type:	Deadman # & Marked	# 4		
Comment:				
Corrective Action:				Date:
Type:	Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.			
Corrective Action:				Date:
Type:	Flow Line	# 1		
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Tank battery #484238				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 250300 Type: WELL API Number: 123-18103 Status: TA Insp. Status: WK

**Workover**

Comment: MIRU Ranger Energy Services e-line, RIH with 5 1/2" 10K CIBP and set @ 4800' KB, POOH with setting tool, RIH with dump bailer and spot 3 sxs of cement slurry on top of CIBP, POOH with dump bailer, RDMO e-line, SIW, SDFN.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697011707	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7146812">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7146812</a>