

# Inspection Photos

API:061-06010

Operator: WESTERN OPERATING COMPANY

Inspection Date: 7/15/2025

County: KIOWA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north toward the access road which will need to be recontoured and reclaimed.



## Inspection Photos



**Photo 2.** Facing north toward the former tank battery location. Reclamation has not been performed.





## Inspection Photos



**Photo 3.** There is a metal flowline culvert that needs to be removed. Flowlines must be abandoned per 1100 rules.



## Inspection Photos



**Photo 4.** Facing northeast toward the wellsite location. There is erosion in this area beginning to occur.





## Inspection Photos



**Photo 5.** Facing northeast at the abandon wellsite. The pumpjack has been removed. The electric power line still remains at the location.



## Inspection Photos



**Photo 6.** Drone aerial photo facing north toward the access road and location.





## Inspection Photos




**Photo 7.** Drone aerial photo overlooking the location disturbance.





## Inspection Photos



**Photo 8.** Facing Drone aerial photo facing northeast. The power line and poles have not be removed.



## Inspection Photos



**Photo 9.** Drone aerial photo facing south.





## Inspection Photos



**Photo 10.** Drone aerial photo facing southeast. There is impacted soils shown at red arrow from historical spill.

