

Inspection Photos

ID:470759

Operator: WESTERN OPERATING COMPANY

Inspection Date: 7/15/2025

County: KIOWA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the access road. There are areas of vehicle rutting that need to be repaired and stabilized with gravel.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:470759 | Date: 7/15/2025

Inspection Photos



Photo 2. Facing north along the access road. Stormwater needs to be diverted off the road. Areas accumulating stormwater need to be built up with BMP's such as roadbase and gravel.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:470759 | Date: 7/15/2025

Inspection Photos



Photo 3. Facing north further along the access road. Areas accumulating stormwater need to be built up with roadbase and gravel.



Inspection Photos



Photo 4. Facing northwest toward the tank battery.



Inspection Photos



Photo 5. Facing south at the remediation area north of the tank battery. This area has mostly undesirable weeds that need to be controlled. This area needs to be reseeded to establish perennial vegetation..

