

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/02/2025

Submitted Date:

07/18/2025

Document Number:

708700118

**FIELD INSPECTION FORM**

Loc ID 324458 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10515  
Name of Operator: GUNNISON ENERGY LLC  
Address: 999 18TH STREET SUITE 1755N  
City: DENVER State: CO Zip: 80202

**Findings:**

2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		geops@oxbow.com	Inspection mail box

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211687	WELL	SI	02/01/2025	GW	051-06009	FEDERAL 10-90-31	EI

**General Comment:**

This is an environmental inspection only. Any previous Corrective Actions not addressed are still applicable. All equipment on site was checked with an RKI GX-6000 gas detector. No fugitive methane was detected at the time of inspection.

**Inspected Facilities**

Facility ID: 211687 Type: WELL API Number: 051-06009 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708700119	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7148425">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7148425</a>