

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/18/2025

Submitted Date:

07/18/2025

Document Number:

698707742

**FIELD INSPECTION FORM**

Loc ID 309370 Inspector Name: Serna, Abe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10369  
Name of Operator: NATURAL RESOURCE GROUP INC  
Address: 801 WEST MINERAL AVE STE 202  
City: LITTLETON State: CO Zip: 80120

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone | Email                       | Comment |
|------------------|-------|-----------------------------|---------|
| De Paolo, Corey  |       | corey.depaolo@state.co.us   |         |
| Serna, Abe       |       | abe.serna@state.co.us       |         |
| Labowskie, Steve |       | steve.labowskie@state.co.us |         |
| Hickey, Mike     |       | michael.hickey@state.co.us  |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 293813      | WELL | SI     | 08/01/2017  | GW         | 071-09451 | MIRAH 1 (OWP) | SI          |

**General Comment:**

[Wellsite Inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | No Sign  |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Good Housekeeping:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               |   |       |  |
| Comment:           | Leaking barrels of oil, unused equipment<br>Oil leak is getting worse with every rain |       |  |
| Corrective Action: |   | Date: |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

|                            |     |       | corrective date |
|----------------------------|-----|-------|-----------------|
| Type: Compressor           | # 2 |       |                 |
| Comment:                   |     |       |                 |
| Corrective Action:         |     | Date: |                 |
| Type: Gas Meter Run        | # 1 |       |                 |
| Comment:                   |     |       |                 |
| Corrective Action:         |     | Date: |                 |
| Type: Horizontal Separator | # 1 |       |                 |
| Comment:                   |     |       |                 |
| Corrective Action:         |     | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | OTHER    | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   | Date:    |           |         |        |

**Paint**

|                  |          |  |  |
|------------------|----------|--|--|
| Condition        | Adequate |  |  |
| Other (Content)  |          |  |  |
| Other (Capacity) | 428 bbl  |  |  |
| Other (Type)     |          |  |  |

| <b>Berms</b>       |             |                     |                     |             |        |  |
|--------------------|-------------|---------------------|---------------------|-------------|--------|--|
| Type               | Capacity    | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
|                    |             |                     |                     |             |        |  |
| Comment:           |             |                     |                     |             |        |  |
| Corrective Action: |             |                     |                     | Date:       |        |  |
| Contents           | #           | Capacity            | Type                | Tank ID     | SE GPS |  |
| METHANOL           | 1           | OTHER               | STEEL AST           |             | ,      |  |
| Comment:           |             |                     |                     |             |        |  |
| Corrective Action: |             |                     |                     | Date:       |        |  |
| <b>Paint</b>       |             |                     |                     |             |        |  |
| Condition          |             |                     |                     |             |        |  |
| Other (Content)    |             |                     |                     |             |        |  |
| Other (Capacity)   | 300 Gallons |                     |                     |             |        |  |
| Other (Type)       |             |                     |                     |             |        |  |
| <b>Berms</b>       |             |                     |                     |             |        |  |
| Type               | Capacity    | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
|                    |             |                     |                     |             |        |  |
| Comment:           |             |                     |                     |             |        |  |
| Corrective Action: |             |                     |                     | Date:       |        |  |
| <b>Venting:</b>    |             |                     |                     |             |        |  |
| Yes/No             | NO          |                     |                     |             |        |  |
| Comment:           |             |                     |                     |             |        |  |
| Corrective Action: |             |                     |                     |             | Date:  |  |
| <b>Flaring:</b>    |             |                     |                     |             |        |  |
| Type               |             |                     |                     |             |        |  |
| Comment:           |             |                     |                     |             |        |  |
| Corrective Action: |             |                     |                     |             | Date:  |  |

**Inspected Facilities**

Facility ID: 293813 Type: WELL API Number: 071-09451 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI  
Wellhead valves are closed

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <a href="#">Barrels on location are gettin worse with the rains. Checked with Flir camera and lazer show no signs of gas leaks</a> | sernaa | 07/18/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 698707743    | Photo       | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7148576">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7148576</a> |