

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2025

Submitted Date:

07/12/2025

Document Number:

693808855**FIELD INSPECTION FORM**Loc ID 316367 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10775Name of Operator: KT RESOURCES LLCAddress: 3381 WESTBROOK LANECity: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Beasley, Nolan		nolan.beasley@state.co.us	UIC Lead

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432692	WELL	TA	10/01/2022	DSPW	103-11961	AHU WYATT 25-43 SWD	TA

General Comment:

Routine UIC inspection.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-288-0560

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	432692	Type:	WELL	API Number:	103-11961	Status:	TA	Insp. Status:	TA

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube:

Pressure or inches of Hg

0

(e.g. 30 psig or -30" Hg)

Previous Test Pressure

MPP

Inj Zone:

OHCRK

TC:

Pressure or inches of Hg

0

Previous Test Pressure

Last MIT:

02/23/2024

Brhd:

Pressure or inches of Hg

0

Previous Test Pressure

AnnMTReq:

Comment:

Routine UIC Inspection. Well temporarily abandoned.

Corrective Action:

Date:

Method of Injection:

PUMP FEED

Test Type:

Tbg psi:

Csg psi:

BH psi:

Insp. Status:

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test:

06/05/2024

Annual Brhd Completed?

No

Last Brhd Test Results

Initial Surf Csg Pressure:

15

Fluid Type:

VAPOR

End Surf Csg Pressure:

0

Comment:

No annual bradenhead test Form 17 on file.

08/15/2025

Corrective Action:

Submit Form 17 as directed by Rule 419.c

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Date Run: 7/19/2025 Doc [#693808855]

Page 3 of 4

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404277282	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7139074
693808860	Inspection photos 7/11/2025	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7139069