

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7318 PAD

Location ID: 315265

Date: 07/16/2025



Photo # 0041 Entrance to location




Photo # 0068 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7318 PAD

Location ID: 315265

Date: 07/16/2025



Photo # 0042 Location



Photo # 0053 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7318 PAD

Location ID: 315265

Date: 07/16/2025



Photo # 0098 SW corner of location



Photo # 0099 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7318 PAD

Location ID: 315265

Date: 07/16/2025



Photo # 0045 Wellhead sign lacks required information/not in compliance with CECMC rules




Photo # 0049 Equipment has been modified and is not being operated in a safe manner

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7318 PAD

Location ID: 315265

Date: 07/16/2025



Photo # 0059 Open ended piping/wildlife hazard/available for entry by wildlife

Photo # 0077 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7318 PAD

Location ID: 315265

Date: 07/16/2025



Photo # 0084 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 0080 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7318 PAD

Location ID: 315265

Date: 07/16/2025



Photo # 0089 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 0093 Failure to minimize erosion & transport of sediment off location/insufficient BMP's