

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 114 Pad

Location ID: 322437



Photo # 2123 From entrance to location




Photo # 2124 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 114 Pad

Location ID: 322437



Photo # 2125 Location



Photo # 2126 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 114 Pad

Location ID: 322437



Photo # 2127 Location




Photo # 2128 Battery sign weathered & becoming illegible & additionally access road info on sign is incorrect

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 114 Pad

Location ID: 322437



Photo # 2129 Hog panels around tank battery damaged